





Foundation has been excavated and rebar added to the existing foundation




New concrete is poured adding width to the foundation.




Crack in brick veneer before the foundation lifting process.



The crack in the brick veneer is now almost completely closed after the lifting process.



Before



After